


3 DETAIL AT BELL & HUB JOINT SCALE:6"=1"-0"



WASA/ODA

a joint venture
ASSOCIATED ARCHITECTS/ENGINEERS
Wank Adams Slavin Associates, L.L.P.
Ohlhausen DuBois Architects

Wank Adams Slavin Associates, L.L.P. 740 Broadway New York, New York 10003 tel. (212) 420-1160 fax (212) 529-9079

Ohlhausen DuBois Architects 14 East 4th Street New York, N.Y. 10012

PERSONAL PACINEES

ROBERT SILMAN ASSOCIATES, P.C. CONSULTING ENGINEERS

88 UNIVERSITY PLACE NEW YORK, NY 10003

Copyright, 2002
by Work Adams Stavin Associates
Architecture Engineering Preservation Facilities
All rights reserved. This drawing may not bereproduced, nor any part theretol, or street in any
reproduced, nor any part theretol, and form or by
any means, electronic, mechanical, photocopying,
recording, or otherwise without prior written
permission of the publisher.
Published By Wark Adams Stavin Associates – WASA

Published By Warsk Adams Stavin Associates -740 Broodway, New York, NY 10003 (212) 420-1160 Printed in the United States of America

Printed in the United States of America

REVISION -

DATE DESCRIPTION

12/27/02 BID SET

HINSDALE ST.

AREA OF WORK

WILLIAMS AVE.

BLOCK NO.: 3699 LOT NO: 1 ZONING: M1-4



City of New York

Department of Design and Construction

DIVISION OF STRUCTURES BUREAU OF ARCHITECTURE & ENGINEERING

CAPITAL PROJECT NO. HH112BWFD

EXTERIOR MASONRY RESTORATION & WINDOW REPLACEMENT AT

BROOKLYN WOMEN'S SHELTER 116 WILLIAMS AVENUE BROOKLYN, NY 11207


DEPARTMENT OF HOMELESS SERVICES

TRANSVERSE SECTION



GENERAL NOTES:

1. CONFIGURATION AND DIMENSIONS OF EXISTING CONSTRUCTION IS BASED ON ORIGINAL CONSTRUCTION DRAWINGS PREPARED IN 1923. CONTRACTOR SHALL VERIFY IN FIELD ALL EXISTING CONDITIONS AND DIMENSIONS PRIOR TO COMMENCEMENT OF WORK.



SPALL REPAIR DETAIL NOTES:

- 1. REPAIRS TO MATCH EXISTING LIMESTONE IN COLOR, PROFILE AND TEXTURE.


 2. REMOVE ALL LOOSE AND DETERIORATED LIMESTONE.

 3. COMPLETE PERPARATION BY WASHING THE SURFACE WITH CLEAN WATER AND A BRISTLE BRUSH ONLY AFTER PROTECTIVE COATING ON ANCHOR IS COMPLETELY DRY.


 4. PREPARE SURFACE AND MIX, APPLY AND FINISH RESTORATION MORTAR IN ACCORDANCE WITH MANUFACTURER'S INSTRUCTIONS AND RECOMMENDATIONS.

 5. BUILD UP PATCHING MATERIAL SLIGHTLY ABOVE ADJACENT MASONRY SURFACE.

 6. AFTER ACHIEVING INITIAL SET, SCRAPE AWAY EXCESS RESTORATION MORTAR UNTIL THE DESIRED PROFILE IS OBTAINED.



TYPICAL LIMESTONE SPALL REPAIR DETAIL



2 ENTRANCE ELEVATION
SCALE: 3/8"=1'-0"

WASA/ODA

a joint venture
ASSOCIATED ARCHITECTS/ENGINEERS Wank Adams Slavin Associates, L.L.P. Ohlhausen DuBois Architects

Wank Adams Slavin Associates, L.L.P. 740 Broadway New York, New York 10003 tel. (212) 420-1160 fax (212) 529-9079

Ohlhausen DuBois Architects 14 East 4th Street New York, N.Y. 10012

ROBERT SILMAN ASSOCIATES, P.C. CONSULTING ENGINEERS

88 UNIVERSITY PLACE NEW YORK, NY 10003

> Copyright, 2002 by Wonk Adoms Slavin Associates Architecture Engineering Preservation Facilities Architecture Engineering Preservation Facalities
> All rights reserved. This drawing may not be
> respondinged, our any part thereof, or stored in
> retirent system or transmitted, in any form or
> only morn, soften with a subtract, photocopying,
> permission of the publisher. Published By Work Adams Slavin Associates -WAS

740 Broodway, New York, NY 10003 (212) 420-1160 Printed in the United States of America

REVISION -

12/27/02 BID SET

HINSDALE ST.

WILLIAMS AVE.

City of New York

Department of Design and Construction

DIVISION OF STRUCTURES BUREAU OF ARCHITECTURE & ENGINEERING

CAPITAL PROJECT NO. HH112BWFD

EXTERIOR MASONRY

RESTORATION & WINDOW REPLACEMENT AT

BROOKLYN WOMEN'S SHELTER 116 WILLIAMS AVENUE BROOKLYN, NY 11207

DEPARTMENT OF HOMELESS SERVICES

ENLARGED ENTRANCE ELEVATION

50222 08/05/2002 C.A. AS NOTED

A-9